





- For reliable measurements, it is important to reduce interference from outside noise on the signals.
- When connecting to other devices, ensure that the integrity of the shielding is maintained.
 - Use shielded cables and wire terminals.